

STATE OF FLORIDA
DEPARTMENT OF HEALTH
COUNTY HEALTH DEPARTMENT
PUBLIC SCHOOL
INSPECTION REPORT



1 of 2

Facility Information

RESULT: Satisfactory

Permit Number: 13-51-08366 Name of Facility: Lorah Park Elem. Address: 5160 NW 31 Avenue City, Zip: Miami 33142 Type: Public School Owner: M-DCSB Food and Nutrition Person In Charge: Maria L. Cavalla Phone: 305-633-1424	Correct By: Next Inspection Re-Inspection Date: None
--	---

Inspection Information

Purpose: Routine Inspection Date: 9/1/2016	Begin Time: 09:40 AM End Time: 11:14 AM
---	--

Additional Information

CENSUS	427
FEMALES	208
MALES	219

As per section 120.695 of the Florida Statutes (FS), this form will serve as a "Notice of Non-Compliance: for any violations noted. Items marked below violate the requirements of Chapters 64E-13 and 64E-11 of the Florida Administrative Code (FAC) and must be corrected within the time period indicated in the "Results" section above. Continued operation of this facility without making these corrections is a violation of Chapter 64E-13 and 64E-11, FAC, and Chapter 381, FS. Failure to correct violations may result in an administrative fine or other legal action being initiated or continued.

Violation Markings

SCHOOL SANITATION 1. School Site 2. Playground Equipment 3. Athletic Equipment BUILDINGS 4. Construction X 5. Maintenance & Repair 6. Lighting/Foot-Candles 7. Heating, Ventilation, A/C 8. Natural Ventilation X 9. Mechanical Ventilation SANITARY FACILITIES X 10. Provided/Accessible	X 11. Cleanliness & Repair 12. Toilet Facilities 13. Separation of Sexes 14. Fixture Ratio X 15. Handwash Facilities 16. Showers/Fixtures 17. Shower Water Temp. WATER SUPPLY 18. Installed/Operated/Maintained X 19. Drinking Fountains 20. Approved Source LIQUID/SOLID WASTE 21. Sewage Disposal	22. Solid Waste VECTOR/VERMIN CONTROL 23. Infestation/Control 24. Brush/Trash 25. Water Collection/Drainage SAFETY 26. First Aid Kit FOOD 27. Food Insp. Rpt. OTHER 28. 29.
---	---	--

General Comments

No General Comments Available
Email Address(es): marialac@dadeteschools.net

Inspector Signature:

Client Signature:

Maria L. LaCavalla

STATE OF FLORIDA
DEPARTMENT OF HEALTH
COUNTY HEALTH DEPARTMENT
PUBLIC SCHOOL
INSPECTION REPORT



2 of 2

Violations Comments

<p>Violation #5. Maintenance & Repair Provide missing ceiling tile in female restroom in room 103-D, in female restroom in room 102-A, in classroom 102-A, in male restroom 211-D, in room 211-A and all other applicable rooms throughout the facility Replace stained ceiling tiles in both male and female restrooms in room 102-D, in both male and female restrooms in room 102-A, in classroom 102-A, in female restroom 213-D and all other applicable rooms throughout the facility Remove peeling paint off wall in room 211-D and all other applicable rooms throughout the facility CODE REFERENCE: Maintenance & Repair 64E-13.004(3)(b)(c). Buildings shall be kept clean and in good repair, free from hazardous conditions, such as loose or broken floor tiles and boards; loose moldings; loose hanging fixtures, pipes, and electric wires; and broken plaster. Furnishings and equipment shall be kept clean and in good repair, free of missing parts and hazards such as sharp edges, splinters, and protruding or rusty nails.</p>
<p>Violation #9. Mechanical Ventilation Provide missing vent cover in female restroom in room 101-D CODE REFERENCE: Mechanical Ventilation 64E-13.004(5)(d). All spaces which do not meet the requirements for natural ventilation shall be mechanically ventilated by means of electrically operated exhausts. Fans and blowers shall be sized and designed to provide the required air movement without excessive or disturbing noise. Special provisions shall be made in the design of ventilation systems in areas of high air contamination such as paint shops, auto repair shops and chemistry laboratories, art rooms where kilns are used, wood working, and metal shops, chemical storerooms. A high capacity emergency exhaust system is recommended for chemistry laboratories. All air conditioned spaces shall be ventilated when occupied.</p>
<p>Violation #10. Provided/Accessible Repair leak at handwashing sink in room 213-A Unclog handwashing sink located by male restroom in room 102-D CODE REFERENCE: Provided/Accessible 64E-13.004(6). Every school plant shall be provided with toilet and hand washing facilities for all occupants. These facilities shall be located for convenient student access and faculty supervision and kept clean and in good repair. Faculty and staff facilities shall be provided in separate rooms from student facilities.</p>
<p>Violation #11. Cleanliness & Repair Eliminate the use of deodorizers in male restroom in room 214-D CODE REFERENCE: Cleanliness & Repair 64E-13.004(6)(a). Walls to a height of at least 4' feet toilet partitions and floor of all toilet rooms shall be finished with impervious materials. All plumbing fixtures shall conform to the provisions of the local plumbing code. All group toilet rooms shall be provided with at least one (1) floor drain and (1) hose bib. The floor shall be sloped to the drain. Deodorizers shall not be used in toilet rooms.</p>
<p>Violation #15. Handwash Facilities Replenish soap at handwashing sink in female restroom 005E CODE REFERENCE: Handwash Facilities 64E-13.004(6)(b). Handwashing facilities shall be located within or adjoining each toilet room. Soap dispensers shall be provided at all wash basins and liquid or powdered soap shall be used. Individual towels, preferably paper shall be used. Use of common or public towels is prohibited. Hot-air hand drying devices</p>
<p>Violation #19. Drinking Fountains Restore water at drinking water fountain in room 103-A, at fountain located next to female restroom in 101-D CODE REFERENCE: Drinking Fountains 64E-13.004(7)(b). Drinking fountains of an approved, sanitary slant jet type shall be provided in the ratio specified in the local building code or Chapter 64E-10, F.A.C. In no case shall fountains be located in any toilet room.</p>

Inspection Conducted By: Naissa Julien (31113)
Work: (305) 623-3500 ex. 24222
Date: 9/1/2016

Inspector Signature:

Handwritten signature of Naissa Julien.

Client Signature:

Handwritten signature of Maria L. LaCivella.